Work Ord Thursday, June												Page 1	
Item ID: Revision ID: Item Name:	D4035-047 Lid Rib Assen	nbly, Aft (Light)		Accept					Setup	Start Stop			
Start Date: Required Date: Reference:	6/10/2010	Start Qty: 2.00 Req'd Qty: 2.00	1841/4   108   1841   1841/4   1841/4   1841/	4.	Cust Item I Customer:	D:							
Approvals:	Process Pla	n:	Date: 16-4-1	Tooling:		ite:			Run	Start Stop			
Sequence ID/ Work Center II	D	Operation Description		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp	
Draw Nbr	Rev	ision Nbr										- Cump	
D4035 100 Large Fab	A	<b>Memo</b> 1- Cut D40. 2- Drill holo 3- remove i	aminum rod Batch: 1138 35-7 as per dwg D4035 c using DT9620 and chamfe dentification marks and deb shing in rib and grind weld to	0.00 or holes as per dwg D4035 urr	SAD	10-0	, ! <b>9</b> -12	<u>a</u>	Cp	<u>L</u> 11	2:07	.21	
110  QC Quality Control		QC9- Inspect visual per  Memo	QSI004- Fusion Welds	0.00			,	ل ک	yD 10	D.OT.	<b>31</b>		

í

1

### **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES** Approval Approval DATE STEP **PROCEDURE CHANGE** By Qty Chief Eng / Date QC Inspector Prod Mar Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_\_ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B **Description of NC** Verification **Approval** DATE **STEP** Approval **Action Description** Sign & Initial Section A QC Inspector Section C Chief Eng Chief Eng Date Chief Eng

# Work Order ID 59734

Thursday, June 10, 2010 10:04:09 AM



Page 2

Item ID:

D4035-047

Accept

Setup Start

Stop



**Revision ID:** Item Name:

Lid Rib Assembly, Aft (Light)

Cust Item ID:

**Customer:** 

**Start Date:** 

6/10/2010 Required Date: 6/17/2010 Start Qty: 2.00 Req'd Qty: 2.00

Date:

Reference:

Approvals:

Process Plan: \_\_\_\_\_ Date: \_\_\_\_

Tooling:

SPC (Y/N):

Set Up/

Date:

Date:

Run

Start Stop

Sequence ID/ Work Center ID

120

Quality Control

Operation Description

QC5- Inspect part completeness to step on W/O

Memo

**Run Hours** 0.00

Tool ID

Tool # Plan Accept Code Qty

Reject **Qty** 

Reject Number

Insp. Stamp

130

Packaging

Packaging

Identify as per dwg & Stock Location: ( A

0.00

0.00

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

Memo

0.00

Dart Ae	rospace i	Ltd					İ	,* ,
W/O:			WC	¥.,.				
DATE	STEP	PR	ROCEDURE CHANGE			Date Q	ty Approval Chief Eng / Prod Mgr	Approva QC Inspect
Part No		PAR #:						
	Res	solution:	Disposition	າ:	_ QA: N/C CI	osed:	Date: _	
NCR:			WORK ORDI	ER NON-CONFORMA	NCE (NCR	)		
DATE	CTED	Description of NC	ion of NC Corrective Action Section B					
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approva QC Inspect
					,			
				•.				
							<b>]</b> .	

<b>Picklist Print</b>					<del></del>				1				+
Thursday, June 10,	2010 10:04:13 AM	1					1						Page 1
Work Order ID: 59	7734	· · · · · · · · · · · · · · · · · · ·							<del></del>		<u>-</u>		
Parent Item: Da	1035-047			''''	] 								(
Parent Item Name:	Lid Rib Assembly,	Aft (Light)	1 (84		al Bill (1881)								
Comments:	IPP RevA: new issue per dwg revA 10.03	ue DD 10.01.25 3.15 verified by:E	verifie EC	d by:EC	IPP Re	ev:B as	ļ		Start Date: 6/10 Start Qty: 2.00		-	d Date: 6/1 ed Qty: 2.0	
Component Item ID/ Item Name D4035-11 Bushing	Replacement Item ID	Mfg/ Purch Manufactured	Bin Item No	Primary Location	Last Location	Route Seq ID 100	Unit of Measure Each	Qty on Hand 18.0000	Qty per Kit	Total Otv 4	Qty Issued	Date Issued	Status
				Location	1	Loc (	<u>Otv</u>	Loc Code	·		ø	•	· · · · · · · · · · · · · · · · · · ·
				ST109	58376		18						
M6061T6TS0.750W.06		Purchased	No		36370	100	18 f	186.0965	1.875	2 047269			
5061-T6 SQ Tube .75 x .7	75 x .062W	1880 <b>1880 1880 188</b> 0 <b>188</b> 0 1880					!	200.0303		3.947368 S( <del>)</del>	0	1.0	- 67 -
				Location	!	Loc C	<u>Oty</u>	Loc Code					
				MAT	444	108.4							
					114573 114640	22.1 86.3			_	<b>A</b>			
				MAT06	111010	77.6	f		_	3.9470	1		
					103069	38.0							
					104422	15.5			_				
					16441 9671	20.0	1.07 263		_				

•

# **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES Approval** DATE Approval STEP **PROCEDURE CHANGE** By Date Qty Chief Eng / QC Inspector Prod Mgr Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_\_ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B **Description of NC** Verification **DATE** STEP **Approval Approval** Sign & Initial **Action Description** Section A Section C QC Inspector Chief Ena Chief Eng Chief Eng Date

DART AEROSPACE LTD	Work Order:	358734 .
Description: Rib AT 9620	Part Number:	14035-047
Inspection Dwg: 14035 Rev: A		Page 1 of 1

# FIRST ARTICLE INSPECTION CHECKLIST

D	1	T	T -	1	- CALIST	
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
22,50	+/_ 0030	22,50			M-T	
_5.95	+1-0.930	5.95	V		M-The	
0.375	+1-0.90	0.372	0/		Vern Vern Vern M-T	
0.625	+/_0.010	0.625	~		Vern	
3.50	+/_ 0.030	3.508	V		Vern	
4.25	+/6.030	4.25	V		M-T	
\$0.125	+ 0.004	0.125	/		Vers	
60.395	+0.006	0.375	\ \		Vern	
450	+/- 1/20	45°	V		Protrator	
····						
					~	
	The second secon					
			·			
	*					

Measured by:	SAD	Audited by:	2	Preliminary Approval:	
Date:	10-07-62	Date:	10/07/12	Date:	

Rev	Date	Change	Revised by	Approved
E	10.04.14	Added preliminary approval	KJ	Approved

\$ 10.04.15

QTY -041 QTY -043 QTY -045 P/N DESCRIPTION D4035-041 LID RIB ASSY, FWD D4035-043 LID RIB ASSY, AFT LID RIB ASSY, FWD (LIGHT) X D4035-045 D4035-047 D D4035-1 RIB D4035-3 RIB D4035-5 RIB D4035-7 RIB D4035-11 BUSHING 6 D2327-3 SPACER BUSHING D2953-175 SPACER D4021-9 BUSHING

SHOP COPY


ENGINEERING

UNCONTROLIED COPY


SUBJECT TO AMENDMENT

WITHOUT NOTICE


WORK ORDER NO. 59734 BS10-6-10




D4035-041 BASKET LID RIB ASSY, FWD



D4035-043 BASKET LID RIB ASSY, AFT



D4035-045 BASKET LID RIB ASSY, FWD (LIGHT)




D4035-047 BASKET LID RIB ASSY, AFT (LIGHT)




Α	NEW IS	SUE		JPH	10.03.04					
REV.			DESCRIPTION	BY	DATE					
DESIGN	1	AJS	DART AEROSPA	DART AEROSPACE LTD						
DRAWN JPH		JPJH	HAWKESBURY, ONTARIO, CANADA							
CHECK	CKED		DRAWING NO.	O/IIV	REV. A					
MFG. A	PPR.	TA.	D4035		SHEET 1 OF 5					
APPRO	VED	W	TITLE		SCALE					
DE APP	DE APPR.		BASKET LID RIB ASSY	BASKET LID RIB ASSY						
DATE	10.0	3.04	COPYRIGHT © 2010 BY DART AEROSPACE LTD THIS DOCUMENT SWAPER AND CONFIDENTIAL AND IS SUPPLED ON THE LOOKE AS CONFIDENT IN IT IT IS NOT TO BE USED FOR ANY PURPLES OR COPYRIGHT ON ANY PURPLES PERSON WITHOUT							


### **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES Approval Approval** DATE STEP PROCEDURE CHANGE By Date Qty Chief Eng / QC Inspector Prod Mar Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_\_ **WORK ORDER NON-CONFORMANCE (NCR)** NCR: **Corrective Action** Section B **Description of NC** Verification DATE **STEP** Approval Approval Initial **Action Description** Sign & Section A Section C Chief Eng QC Inspector Chief Eng Chief Eng Date




Dart Ae	rospace Li	td						, ,
W/O:			WC		;			
DATE	STEP	PROCEDURE CHANGE By Date						Approva QC Inspect
Part No		PAR #:						
	Reso	olution:	Disposition	1:	_ QA: N/C C	losed:	Date: _	
NCR:			WORK ORDE	ER NON-CONFORMA	ANCE (NCF	R)		
DATE	OTED	Description of NC		<b>A</b>				
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		Approval Chief Eng	Approva QC Inspect
				. v - 1				



Dart Ae	erospace L	.td						, 3
W/O:			WC	RK ORDER CHANGES	3			
DATE	STEP	PR	PROCEDURE CHANGE				Approval Chief Eng / Prod Mgr	Approva QC Inspecto
Part No	Part No: PAR #:							
	Resolution:			1:	QA: N/C Clo	sed:	Date: _	
NCR:			WORK ORDE	R NON-CONFORMAN	CE (NCR)	)		
DATE	STEP	Description of NC		Corrective Action Section I		Verification	on Approval	Approva
	-	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto
-								



# **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES Approval** Approval QC Inspector DATE STEP PROCEDURE CHANGE By Date Qty Chief Eng / Prod Mgr Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_\_ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B **Description of NC** Verification **Approval** DATE **STEP Approval** Sign & Initial **Action Description** Section A QC Inspector Section C Chief Eng Chief Eng Chief Eng Date



### **Dart Aerospace Ltd** W/O: **WORK ORDER CHANGES Approval Approval** DATE STEP **PROCEDURE CHANGE** By Date Qty Chief Eng / Prod Mgr QC Inspector Part No: \_\_\_\_\_\_ PAR #: \_\_\_\_ Fault Category: \_\_\_\_\_ NCR: Yes No DQA: \_\_\_\_ Date: \_\_\_\_\_ Resolution: \_\_\_\_\_ Disposition: \_\_\_\_ QA: N/C Closed: \_\_\_\_ Date: \_\_\_\_\_ WORK ORDER NON-CONFORMANCE (NCR) NCR: **Corrective Action** Section B **Description of NC** Verification Approval DATE **STEP Approval Action Description** Sign & Initial Section A QC Inspector Section C Chief Eng Chief Eng Chief Eng Date